Window	Tenderer 1 ARK	Cost	Tenderer 2 Stained Glass restoration	Cost
WS3	remove lights complete	£3,000.00	remove two lights	no breakdown
	board up	13,000.00	remove two lights	110 bi cakaowii
	new glass "to match original as			
	closely as possible" 61 quuarries			
	redcorate 12 saddle bars , refit & point in NHL mortar			
	opt tip saddle bars in s/s	£600.00		
WS3a	New window	£400.00	new window	no breakdown
	quarries /cames to match existing if some found			
WS5	Remove 3 lesded lights complete and board up	£2,450.00	remove 3 base panels 3 x in situ repairs to high level	no breakdown
	26 quarries/ redecorate saddle bars			
	refit and point in NHL mortar			
	Option: re-tip saddle bars in s/s	£450.00		
WS05	9 in-situ repairs	£580.00	9 repairs	no breakdown
WS07	Option 2 repair	£850.00	13 repairs	no breakdown
	Option. Tip saddle bars in s/s	£150.00		
		CO 400 00		644 500 643 500
		£8,480.00		£ 11, 500 - £ 12 500 not VAT registered
	remove 2/3 days	access allowed for -	All panels replaced with	i not viti registered
	remove 2/3 days	l control of the cont	polycarbonate or plywood.	
		2	Metal wlork painted with	
		these relatively low	rust inhibiting	
		jobs.	paint.reporinted in with lime morat	
		We'd be dismantling		
		each night, obviously		
		when we are on site		No access allowed fo
		for a two or three		
		consecutive days,		
		we'd like to be able to		
		leave the scaffold over		
		night in the church."		
	refit 6 weeks later			
		<u>}</u>		•
		İ	<u> </u>	: